Swo
Tr Burfamon

Yehrer EF

Lake Michigan District Headquarters
Box 3600
Green Bay, Wisconsin 54303

September 24, 1974

Mr. James Lehrer

Mr. James Lehrer
Lehrer Sanitary Service #73
Town of Buchanan, Outagamie County
1604 Crooks Avenue
Kaukauna, Wisconsin 54130

Dear Mr. Lehrer:

On September 23, 1974, myself and Gary Kulibert inspected your landfill to determine if you had complied with the provisions of Order #2A-74-833. We stopped at your office to see if you would accompany us on the inspection, however, your secretary said you were out for the day. Our inspection disclosed that you have not complied with the order.

- 1. All solid waste was not being covered daily. Paper mill sludge had been dumped near the present active area. That material was not being covered daily. In addition, solid waste was sticking through the cover material in several areas of the site.
- All the paper mill sludge in the upper portion of the landfill had not been compacted and covered. In fact, a truck was dumping additional sludge during our inspection.
- 3. The areas within 300 feet of Kankapot Creek have not been abandoned in accordance with NR 151.12(10) (1-4).
- 4. The landfill has not been screened on the northern side to screen it from view from the adjacent residences.
- 5. All salvageable materials have not been removed from the site. A large pile of metal, approximately 25 cars, and approximately 100 engine blocks and transmissions were still present.

Based on the above violations, I have no alternative but to refer the order to the Attorney General.

Very truly yours,

Lawrence F. Boehm Natural Resource Specialist

LFB:sh cc: SWMS 00671

September 24, 1974

4400

TO:

John Reinhardt

FROM:

Lawrence F. Boehm

SUBJECT:

Referral of Order #2A-74-833 - James Lehrer

On September 23, 1974, myself and Gary Kulibert inspected the James Lehrer SLF to determine if he had complied with Order #2A-74-833. The results of that investigation are listed below. Each Number and letter refers to the corresponding provision of the order.

- 1a. No solid waste was being dumped within 300 feet of Kankapot Creek. However, on September 3, 1974, I witnessed a load of tree trimmings and logs being dumped within 300 feet of Kankapot Creek.
- lb. No disposal of solid waste is being dumped into surface water on the site.
- lc. All newly arriving wastes are not being covered on a daily basis. Paper mill sludge is being dumped near the present active area. This material is not being covered daily. In addition, solid waste is sticking through the cover material in several areas of the site.
- 2. The ponds of leachate and surface water on the site have been filled as prescribed. However, one area of ponded leachate was still present during my September 3, 1974, inspection.
- 3a. All paper mill sludge wastes have not been compacted and covered. In fact, no work has been done in that area.
- 3b. All exposed wastes other than paper mill sludge have not been covered with six inches of earth.
- 3c. All areas within 300 feet of Kankapot Creek have not been abandoned in accordance with NR 151.12(10)(1-4).
- 3d. The facility is not screened on the northern side to screen it from view from the surrounding residences.
- 4. Engineering plans were submitted by the date ordered.



- 5a. All salvageable material has not been removed from the site.
  A large pile of metal, approximately 25 cars, and approximately
  100 engine blocks and transmissions were still present.
- 5b. The site has not been abandoned.

This office is recommending that the order be referred to the Attorney General for prosecution of the violations.

Lawrence F. Boehm			
LFB:sh			
APPROVED:			
Allan F. Schoen			
NOTED:			
	Dete		